Tech Service Products

1110 S. FM 1788 #42
Phone: (432) 296-4992 Email: Chad@tspndt.com
Midland,TX 79706

Certificate of Calibration

Certificate No TSPW-10272026-004

Gage ID	PEA-107230
Gage S/N	107230
Description	Profile Gauge
Operating Procedure:	Visual
Unit of Meas.	
Manufacturer	PMC Lone Star
Cal. Date	10/27/2026
Next Due	10/27/2029
Cal. Freq.	3.00 Years
Location	Lab

Environmental Conditions

Temperature	68 Deg F +/- 2
Humidity	20-55%
Approved	Yes
Customer Info.	Peak NDT Solutions

Certification Statement

TSP Calibration, Inc. calibration systems complies with the requirements of ISO 9001:2015. The equipment that is certified by this certificate has been calibrated by standards that have accuracy which is traceable to standards of the National Institute of Standards and Technology.

Findings

Order No. 1067364 Job No. 261027-2

As Found: Pass As Left: Pass

Damage: Pass
Wear: Pass
Flatness: Pass
Issues that would hinder performance or readings: None

Calibrated By Chad Adams **Signature** _____ **Date:** 10/27/2026

APPROVED
By Kayla Myers at 11:47 am, Oct 29, 2026

Tech Service Products

1110 S. FM 1788 #42
Phone: (432) 296-4992 Email: Chad@tspndt.com
Midland,TX 79706

Certificate of Calibration

Certificate No TSPW-10272026-005

Gage ID	PEA-108572
Gage S/N	108572
Description	Profile Gauge
Operating Procedure:	Visual
Unit of Meas.	
Manufacturer	PMC Lone Star
Cal. Date	10/27/2026
Next Due	10/27/2029
Cal. Freq.	3.00 Years
Location	Lab

Environmental Conditions

Temperature	68 Deg F +/- 2
Humidity	20-55%
Approved	Yes
Customer Info.	Peak NDT Solutions

Certification Statement

TSP Calibration, Inc. calibration systems complies with the requirements of ISO 9001:2015. The equipment that is certified by this certificate has been calibrated by standards that have accuracy which is traceable to standards of the National Institute of Standards and Technology.

Findings

Order No. 1067364 Job No. 261027-2

As Found: Pass As Left: Pass

Damage: Pass
Wear: Pass
Flatness: Pass
Issues that would hinder performance or readings: None

Calibrated By Chad Adams **Signature** _____ **Date:** 10/27/2026

APPROVED
By Kayla Myers at 11:48 am, Oct 29, 2026

Tech Service Products

1110 S. FM 1788 #42
Phone: (432) 296-4992 Email: Chad@tspndt.com
Midland,TX 79706

Certificate of Calibration

Certificate No TSPW-10272026-006

Gage ID	PEA-108403
Gage S/N	108403
Description	Profile Gauge
Operating Procedure:	Visual
Unit of Meas.	
Manufacturer	PMC Lone Star
Cal. Date	10/27/2026
Next Due	10/27/2029
Cal. Freq.	3.00 Years
Location	Lab

Environmental Conditions

Temperature	68 Deg F +/- 2
Humidity	20-55%
Approved	Yes
Customer Info.	Peak NDT Solutions

Certification Statement

TSP Calibration, Inc. calibration systems complies with the requirements of ISO 9001:2015. The equipment that is certified by this certificate has been calibrated by standards that have accuracy which is traceable to standards of the National Institute of Standards and Technology.

Findings

Order No. 1067364 Job No. 261027-2

As Found: Pass As Left: Pass

Damage: Pass
Wear: Pass
Flatness: Pass
Issues that would hinder performance or readings: None

Calibrated By Chad Adams **Signature** _____ **Date:** 10/27/2026

APPROVED
By Kayla Myers at 11:50 am, Oct 29, 2026